


GAS SPRINGS - INSTALLATION GUIDELINES

Mounting examples

Mounting possibilities for gas springs are listed below.

For additional information on mounting, see the corresponding pages in the catalogue.



Fixed with 2480.044./045./047.


Fixed with 2480.022.



GAS SPRINGS - INSTALLATION GUIDELINES

To achieve the best possible service-life and safety from the gas spring, the directions below must be followed.

Mounting instructions



- Secure the gas spring to the tool/machine whenever possible, using the threaded hole(s) in the base of the gas spring or a suitable flange.
 Never exceed the maximum torque values for the threads in the base of the gas spring: (M6 = 10 Nm; M8 = 24 Nm; M10 = 45 Nm; M12 = 80 Nm)
- The threaded hole in the piston rod top should not be used for mounting purposes. It is only to be used when carrying and servicing the gas spring.
- Do not use the gas spring in such a way that the piston rod is realised freely from its compressed position, as this could cause internal damage to the gas spring.r).
- Make sure the gas spring is mounted parallel to the direction of the compression stroke.
- Ensure the contact surface of the piston rod top is perpendicular to the direction of the compression stroke and is sufficiently hardened.
- The gas spring should not be subjected to the side loads.
- Protect the piston rod against mechanical damage and contact with fluids.
- We recommend providing a stroke reserve of 10% of the nominal stroke length or 5 mm.
- The maximum charging pressure as a function of the working temperature must not be exceeded as it may effect the safety of the product.
- Exceeding the gas spring's recommended operating temperature will shorten the service-life of the gas spring.
- The entire contact surface of the piston rod / piston should be used.
- Do not remove bottom 2480./2497.00.20. from spring until all gas pressure has been discharged.